



1. Tree branch laid across water course
2. Sheep Hurdles, including fences and gates installed across Water course, along with a low bridge across the water course (See below images)
3. Further sheep fencing and mesh across the water course, along with some farm rubbish including tractor tyres.
4. Narrow bridge brick arch which is restricting flow and means large amounts of debris is been dropped as shown in the images.
5. Agricultural ford crossing
6. Agricultural ford crossing across river
7. Unknown wooden bridge disused and overgrown. Looks rotten and may give way in the future.
8. Fallen Trees in water course perturbing from the bank and low hanging bushes.
9. Damage to bridge separation between arch and parapet

Photos

<p>Location (2)</p>			
<p>Location (3)</p>			
<p>Location (4)</p>			

Location  
(5)




Location  
(8)



Location  
(9)










A number of Trees within this area on the highway side require a tree survey as they look to have a disease

A number of sandbags found within the watercourse required to be removed as they are within the concrete channel

Unable to survey as very overgrown with nettles and brambles and restricted access

0 30 60m





Number of fallen trees on the Highway side blocking the watercourse in a number of places with potential for further blocking. Damaged hand rail near recreation ground where a tree has fallen.

Overgrown with small trees and bushes requires some maintenance

